

[January 2018 Lead2pass 2018 100% Real 220-901 Exam Questions 1346q

Lead2pass 220-901 Exam Questions Guarantee 220-901 Certification Exam 100% Success:

<https://www.lead2pass.com/220-901.html> QUESTION 1 Which of the following would likely be the MOST cost-effective media to use for storing 8GB of data? A. DVD RWB. CD-ROMC. Tape backupD. DVD+R DL Answer: D QUESTION 2 A technician is troubleshooting an expansion card in a computer that allows the computer to receive faxes over a VoIP line. The line connected to the expansion card is MOST likely which of the following cable types? A. CoaxialB. CAT3C. CAT6D. Multi-mode fiberE. Single-mode fiber Answer: C QUESTION 3 A user reports that the cursor jumps to random screen locations when typing on a laptop computer. Which of the following devices is MOST likely causing this? A. The touchpadB. The mouse wheelC. The multimedia keysD. The digitizer Answer: A QUESTION 4 An IT manager needs to install a large display in a front office area with a lot of natural light. Which of the following display technologies will BEST satisfy the requirements of the design plan? A. CRTB. CCFL LCDC. IPS LCDD. LED LCD Answer: D QUESTION 5 A network technician connects a tone generator to an RJ-45 drop. Which of the following is the MOST likely reason for doing this? A. To validate proper wiring of the network jackB. To confirm continuity of the conductorsC. To locate the position of the cable on a patch panelD. To test the transmission quality of the connection Answer: C QUESTION 6 A technician receives a call that a client's PC is not booting after a recent test of the building's back-up generators. When the technician arrives, it is discovered that, once powered on, there is no output display or POST beep codes. Furthermore, after 15 seconds, the system's fans begin running much louder and faster. Which of the following is the MOST likely issue? A. The motherboard was damaged by the power test.B. The PC's RAM was affected by ESD.C. The power supply was damaged and is nonfunctional.D. The hard drive was erased due to the power test. Answer: A QUESTION 7 A computer technician is responding to a call about a printer that is causing streaks to appear on every printout. Which of the following is the MOST likely cause? A. Duplex unitB. Toner cartridgeC. Imaging drumD. Pickup rollers Answer: C QUESTION 8 A technician needs to boot a PC from a USB drive. Which of the following settings should be disabled to accomplish this task? A. Fast BootB. UEFI Admin PasswordC. Secure BootD. Legacy Boot Answer: C QUESTION 9 Which of the following types of expansion slots is MOST frequently found in blade servers? A. PCIeB. PCIC. PCI-XD. miniPCI Answer: C QUESTION 10 A user has requested a device that could be used for web-conferences while away from work. The device will mainly be used for emailing, document reviewing, and phone calls. Which of the following mobile devices would a technician MOST likely recommend? A. TabletB. Smart cameraC. PhabletD. Web camera Answer: C

220-901 dumps full version (PDF&VCE):

<https://www.lead2pass.com/220-901.html> **Large amount of free 220-901 exam questions on Google Drive:**

<https://drive.google.com/open?id=0B3Syig5i8gpDb0M0dHJiMS1ZZXM> You may also need: 220-902 exam dumps:

<https://drive.google.com/open?id=0B3Syig5i8gpDMU1VNVhHQ08xR1E>